

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

	Type	L #	Hits	Search Text	Dbs	Time Stamp	Comments	Error Definition	Errors
1	BRS	L1	82	(ambula\$ wheelchair handica\$) and ((wheel with caster) with (adjust\$ mov\$ slid\$)) and (rail handle) and sleeve and (ramp surface)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:18			0
2	BRS	L2	28	5/81.1RP.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:32			0
3	BRS	L3	92	5/81.1HS.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:54			0
4	BRS	L4	231	5/81.1R.ccls. and (wheel caster)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:34			0
5	BRS	L5	163	5/81.1R.ccls. and (wheel caster) and (handle rail handlebar)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:37			0
6	BRS	L6	44	5/81.1R.ccls. and ((wheel caster) with vertical\$) and (handle rail handlebar)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:38			0
7	BRS	L7	22	5/\$.ccls. and ((wheel caster) with vertical\$) and (handle rail handlebar) and (ramp)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:50			0

Type	L #	Hits	Search Text	Dbs	Time Stamp	Comments	Error Definition	Errors
8 BRS	L8	41	((wheel caster) with vertical\$) and ((handle rail handlebar) same (sleeve)) and (incline\$ with ramp)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:51			0
9 BRS	L9	28	5/81.1rp.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:59			0
10 BRS	L10	10	2975435.URPN.	USPAT	2004/05/20 17:57			0
11 BRS	L11	454	5/86.1.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 18:09			0
12 BRS	L12	519	(14/\$.ccls. 5/\$.ccls.) and (vertical\$ with (caster wheel))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 18:10			0
13 BRS	L13	255	(14/\$.ccls. 5/\$.ccls.) and (vertical\$ with (mov\$ adjust\$) with (caster wheel))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 18:18			0
14 BRS	L14	124	(14/\$.ccls. 5/\$.ccls.) and ((foot with pedal) same (caster wheel))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 18:35			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errors
15 BRS	L15	144	(14/\$.ccls.) and (foot 5/\$.ccls.) and (foot with (lever actuator pedal) same (caster wheel)) and (handrail rail\$ handle handlebar)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 19:16			0
16 BRS	L16	562	(ramp dolly wheelchair) and (foot with (lever actuator pedal) same (caster wheel))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 19:25			0
17 BRS	L17	18	(ramp dolly wheelchair) and (foot with (lever actuator pedal) same (caster adj wheel))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 19:42			0
18 BRS	L18	2	4793445.pn.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 19:40			0
19 BRS	L19	6	4793445.URPN.	USPAT	2004/05/20 19:41			0
20 BRS	L20	21	(foot with (lever actuator pedal) same (caster adj wheel) same (rais\$ and lower\$))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 19:43			0
21 BRS	L23	11	4922560.URPN.	USPAT	2004/05/20 19:52			0

Type	L #	Hits	Search Text	Dbs	Time Stamp	Comments	Error Definition	Errors
			("2582143" "2878078" "2757388" "3041636" "3085258" "3259427" "3272530" "3591874" "3438642" "3739793" "4157593" "4279043" "4314576" "4474202" "4474202" "4491193" "4510633" "4763756").PN.	USPAT	2004/05/20 19:52			0
22	BRS	L24 17						
23	BRS	L25 28	4314576.URPN.	USPAT	2004/05/20 19:54			0
			("2757388" "2792874" "2759525" "3158398" "3158398" "3398974" "3354893" "3477673").PN.	USPAT	2004/05/20 19:57			0
24	BRS	L28 7						
25	BRS	L29 18	3591874.URPN.	USPAT	2004/05/20 19:57			0
26	BRS	L32 16	3272530.URPN.	USPAT	2004/05/20 19:58			0
			("2596055" "3272530" "2757388" "3739793" "3739793" "4314576" "4111445" "4844107" "4844107" "4948156" "4894871" "4964182" "4964182" "4995412" "4987622" "5007618" "5007618" "5086798" "5086798" "5201333" "5201333" "5226439").PN.	USPAT	2004/05/20 19:59			0
27	BRS	L35 17						
28	BRS	L36 7	5449013.URPN.	USPAT	2004/05/20 19:59			0

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Error Counts
29	BRS	L37	9	(incline\$ with ramp) and ambulance and (caster wheels)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 20:01		0
30	BRS	L38	72	(ramp) and ambulance and (caster wheel)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 20:04		0
31	BRS	L39	14	(incline\$ with ramp) and (caster with wheel) and (sleeve same (rail handle handlebar railing handrail))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 20:05		0
32	BRS	L40	14	(incline\$ with ramp) and (caster with wheel) and (sleeve same (rail handle handlebar railing handrail))	USOCR	2004/05/20 20:06		0
33	BRS	L41	183	(incline\$ with ramp) and (wheel) and (sleeve same (rail handle handlebar railing handrail))	USOCR	2004/05/20 20:07		0
34	BRS	L42	183	(incline\$ with ramp) and (wheel) and (sleeve same (rail handle handlebar railing handrail))	USOCR	2004/05/20 20:09		0
35	BRS	L43	130	(incline\$ with ramp) and (wheel) and (sleeve same (rail handle handlebar railing handrail))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 20:11		0

Type	L #	Hits	Search Text	Dbs	Time Stamp	Comments	Error Definition	Errors
36 BRS	L45	14	(incline\$ with ramp) and (wheel) and (rail handle handlebar railing handrail) and invalid	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 20:18			0
37 BRS	L46	5	(incline\$ with ramp) and (wheel) and (rail handle handlebar railing handrail) and invalid	USOCR	2004/05/20 20:18			0
38 BRS	L47	1	(incline\$ with ramp) and (wheel) and (rail handle handlebar railing handrail) and handicapped	USOCR	2004/05/20 20:19			0
39 BRS	L48	55	(incline\$ with ramp) and (wheel) and (rail handle handlebar railing handrail) and handicapped	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 20:29			0
40 BRS	L49	75	14/72.5.ccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 20:29			0

Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
1 BRS	76	"5435028" "5231721" "5257426" "4279043" "3911509" "5354022" "5347666" "5507044" "5579864" "4550802"	USPAT	2004/05/20 14:17		
2 BRS	41	("5435028" "5231721" "5257426" "4279043" "3911509" "5354022" "5347666" "5507044" "5579864" "4550802") and (wheel caster)	USPAT	2004/05/20 14:21		
3 BRS	33	("5435028" "5231721" "5257426" "4279043" "3911509" "5354022" "5347666" "5507044" "5579864" "4550802") and (wheel caster) and (rail handle)	USPAT	2004/05/20 14:21		

	Type	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
			("5435028" "5231721" "5257426" "4279043" "3911509" "5354022" "5347666" "5507044" "5579864" "4550802") and (wheel caster) and (rail handle)	USPAT	2004/05/20 14:26		
4	BRS	33					
			("3591874" "4314576" "4843661" "4894871" "4922560" "5226439" "5295498" "5347666" "5435028" "5449013" "5499645" "5509152" "5509432" "5647602" "5787515" "5794284" "5950258" "5983911").PN.	USPAT	2004/05/20 14:22		
5	BRS	18					
6	BRS	1	6170501.URPN.	USPAT	2004/05/20 14:24		
7	BRS	198	(ambula\$ wheelchair handicap\$) and (wheel with caster) and (rail handle) and sleeve and (ramp surface)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/05/20 17:17		

	Errors
4	0
5	0
6	0
7	0